



FFL 90.600

- Revisions**
- F Information Issue 03.06.05
 - F Status change to T1. Issued for Information 10.06.05
 - G Standalone Phase 1. Status change to CD. 07.10.05
 - H Phase 2A added. University room numbers added. 11.11.05
 - I Atrium & circular stairs updated. Corridor width amended. Seismic lifts updated. Mini Forum walls amended.
 - J Lift shafts + car updated. 17.03.06
 - J Specialist Joinery design development 14.07.06
 - K Steel updated to match BH drawings. Pantries and coffee points updated. Status change to CA. 11.08.06
 - L Window at gridlines K & 25 corrected 06.10.06
 - M Printing areas updated 18.10.06
 - N Core D windows adjusted. 23.10.06
 - O Printing area wall moved. M&E risers added. Lockers shown. Structure checked. Stair SP04 updated. 29.11.06
 - P Door positions checked. 05.12.06
 - Q 06.05.07 CQP Changes. Timber panelling omitted. Return air path omitted. Door dimensions adjusted. Window to printing area omitted.
- Notes**

- Roofing Notes**
- Direction of fall of roof membrane
 - RWO Rainwater outlet
 - RWP Rainwater downpipe
 - OF Rainwater overflow
 - SVP Soil vent pipe

**Bennetts Associates
Architects**

- 3 Boroughloch Square Edinburgh EH8 9NJ
- Tel: +44 (0)131 667 7351
- Fax: +44 (0)131 662 1867
- E-mail: potterrow@bennettsassociates.com

Project
**Potterrow Development
for University of Edinburgh**

| | | | | |
|--|---------------------|-------------------------|------------------|--------------|
| Drawing Title Phase 1 Second Floor Plan | job no. 0312 | drawing no. A(E)-102 | rev Q | status CA |
| | scale @ A3 1:200 | scale @ A1 1:100 | date Oct 2004 | |